



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
CHATSWORTH ROAD	O/S 31	TR: Felling	Kerbs missing, unable to repair without tree damage	Tilia x europea	Plant in existing pit o/s 31 (same position as felled tree)	Tilia 'Rancho'
CHATSWORTH ROAD	O/S 33	TR: Felling	F/W uplifted and kerbs pushed - unable to replace	Tilia x europea	Plant in existing pit o/s 33 (same position as felled tree)	Tilia cordata 'Rancho'
CHATSWORTH ROAD	O/S 35	TR: Felling	Kerbs disrupted - unable to replace	Tilia x europea	Plant in existing pit o/s 35 (same position as felled tree)	Tilia cordata 'Rancho'
CHATSWORTH ROAD	O/S 43	TR: Felling	Kerbs, f/w and edgings all disrupted	Tilia x europea	Plant in existing pit o/s 43 (same position as felled tree)	Tilia cordata 'Rancho'
CHATSWORTH ROAD	O/S 47	TR: Felling	F/W and kerbs displaced, no way to work around without root damage	Tilia x europea	Plant in existing pit o/s 47 (same position as felled tree)	Tilia cordata 'Rancho'
CHATSWORTH ROAD	O/S 49	TR: Felling	Kerbs displaced, unable to reset without root damage	Tilia x europea	Plant in new pit centrally o/s 49 (slight relocation to match rest of street)	Tilia cordata 'Rancho'
CHATSWORTH ROAD	O/S 51	TR: Felling	Kerbs and f/w disrupted, completely unable to repair	Tilia x europea	Plant in existing pit o/s 51 (same position as felled tree)	Tilia cordata 'Rancho'